

# IMPORTANT RECALL NOTICE

## Carbon Forks On Certain 2012 Model Year Specialized Bicycles:

► 2012 Tricross Comp   ► 2012 Tricross Sport

The brake boss housed in the Advanced Group carbon fork can disengage from the fork and allow the brake assembly to contact the wheel spokes while rotating, posing a fall hazard.

Sold from July 2011 to November 2011.

### **Remedy:**

Stop riding affected bicycles immediately and return your bicycle to an Authorized Specialized Retailer for a free replacement fork.

If you have any questions contact Specialized at:

**(877) 808-8154**

or visit their web site at:  
**[www.specialized.com](http://www.specialized.com)**