

SAFETY RECALL NOTICE

Model Year 2012 – 2015 Carbon Aerobar With Aero Stem and Hydroformed Alloy Aerobar



Fig. 1: Carbon Aerobar With Aero Stem



Fig. 2: Hydroformed Alloy Aerobar

Hazard: The extension clamp bolt on the Aerobars may break, which could result in the rider losing control and sustaining serious personal injuries.

This is a Safety Recall Notice regarding:

Products	Model Years
Carbon Aerobar with Aero Stem	2012-2015
Hydroformed Alloy Aerobar	2012-2015

Remedy: The affected Aerobars were sold as aftermarket equipment and original equipment on all Model Year 2012 – 2015 Shiv Tri models and the Model Year 2013 Transition Apex model. This notice does not apply to Shiv TT models or the Shiv Low-Stack Aerobar Clamp Set. Stop riding the affected products immediately and return them to an Authorized Specialized Retailer, which will replace the Aerobar Extension Riser Clamp, Pad Holder Clamp, Extension Riser Cap, Extension Riser Cap Nut, and Extension Clamp Bolt with a free new Aerobar Extension Clamp Kit. For any inquiries, call Specialized Bicycle Components, Inc. at:

800-722-4423

(8 a.m. to 6 p.m. MST Monday through Friday)

or online at www.specialized.com

In cooperation with the U.S. Consumer Product Safety Commission

Post until July 25, 2015

SAFETY RECALL NOTICE